## **ERWIN**

82, Nutts Corner Road, Crumlin, Crumlin, BT 29 4SJ 028 9082 5477

## Claas Arion 620 CIS | 2013

ΡΟΑ



## **Vehicle Features**

Air Conditioning, Cab Suspension, Condition: Good, Drive Type: Mechanical, Engine Type: Engine EGR, Front Linkage, Front PTO, Front Tyre Size / Condition: 420/85/R28 CEAT FARM MAX 10%, Pick Up Hitch, Rear Tyre Size / Condition: 520/85/R38 BKT AGRIMAX 20%, Road Speed: 40 KPH, Spools Front: 1, Spools Rear: 4

