82, Nutts Corner Road, Crumlin, Crumlin, BT 29 4SJ 028 9082 5477

ERWIN

Claas Ares 566RZ | 2005

POA

Vehicle Features

Condition: Good, Drive Type: Mechanical, Eco PTO, Engine Type: Engine EGR, Front Tyre Size / Condition: 440/65/28 Michelin 30%, Pick Up Hitch, Rear Tyre Size / Condition: 540/65/38 Michelin 40%, Road Speed: 40 KPH, Spools Rear: 2

